

FLU 300

## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET/CONTROL-U.S.OFFICIALS ONLY

SECURITY INFORMATION

50X1-HUM

COUNTRY	Poland	REPORT	
SUBJECT	Gdynia Repair Shipyard	DATE DISTR.	6 November 1953
		NO. OF PAGES	5
DATE OF INFO.		REQUIREMENT NO.	RD 50X1-HUM
PLACE ACQUIRED		REFERENCES	

THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE.  
THE APPRAISAL OF CONTENT IS TENTATIVE.  
(FOR KEY SEE REVERSE)

50X1-HUM

1. Following the reorganization of the shipyard industry in September 1952, the Gdynia Fishing Craft Shipyard (Gdynska Stocznia Rybacka) and Ships' Repair Service (Remontowa Obsluga Statkow) were merged into one enterprise under the name Gdynia Repair Shipyard (Gdynska Stocznia Remontowa).
2. The new shipyard now overhauls minor floating units (e.g., fishing craft and cutters), and constructs new fishing cutters.
3. The shipyard employs approximately 1,000 workers, working in two shifts.
4. The production plans stipulated that the shipyard's stores were to be supplied with building materials to the value of 9 million zloty, but actually only 6 million zloty worth of materials could be collected. The most acute shortages are: iron sheets; non-ferrous metal goods; spares for engines; steel rods; T-, L-, H-shaped iron; rivets; electric cables and flex; and hardwood. These shortages are caused by delays in deliveries from factories; they, in turn, blame the National Bank, which finances all orders and fails to pay accounts on time.
5. The shipyard is unable to manufacture certain goods due to the lack of the necessary installations or experts. Such goods are therefore ordered from other mechanical workshops, some of which are still privately owned.
6. When orders are placed with the latter, the commercial name of the firm is never mentioned in the shipyard's books, only symbols are used. Symbols are also shown in all production reports. The following are some of the symbols in use:

Symbol

SO 1 - Gdanska Fabryka Maszyn i Odlewow (Gdansk Casting and Machinery Factory) ul. Grunwaldzka 216, Gdansk-Wrzeszcz

SO 2 - Fabryka Maszyn i Odlewow Zeliwnych (Cast Iron and Machinery Factory) ul. Dybowo 26, Gniw.

SECRET/CONTROL-U.S.OFFICIALS ONLY

STATE	X	ARMY	X	NAVY	Ev	X	AIR	X	FBI		AEC		ORR	EV	X		
-------	---	------	---	------	----	---	-----	---	-----	--	-----	--	-----	----	---	--	--

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)

SECRET/CONTROL-U.S. OFFICIALS ONLY

- 2 -

- SO 4 - Gdanskie Zakłady Sprzetu Okretowego (Gdansk Maritime Equipment Plant), Grobla Angielska 3/5, Gdansk.
- SO 5 - Szczecińska Fabryka Sprzetu Okretowego (Szczecin Maritime Equipment Factory), ul. Lady 12/14, Szczecin.
- SO 8 - Wloclawska Fabryka Maszyn Rolniczych (Wloclawek Agricultural Machinery Factory), ul. Torunska 26/28, Wloclawek.
- SO 9 - Zakłady Mechaniczne i Odlewow Zeliwnych (Cast Iron and Mechanical Works), Barlinek.
- SO 10- Bydgoskie Zakłady Sprzetu Okretowego (Bydgoszcz Maritime Equipment Plant), ul. Slusarska 2, Bydgoszcz
- SO 11- Grudziackie Warsztaty Mechaniczne i Odlewow Zeliwnych (Grudziadz Mechanical and Cast Iron Works), ul. Staszycza 4, Grudziadz.

SECRET/CONTROL-U.S. OFFICIALS ONLY

SECRET/CONTROL-U.S.OFFICIALS ONLY

- 3 -

Legend

1. Cutter hull shop, with installations for simultaneous construction of four cutters.
- 1a.)
- 1b.) On ground floor: machines for processing timber, viz: two band saws, one circular saw, one roughing plane and two smoothing planes.
- 1c. First floor: Design offices
2. Locksmith's shop: ground floor - installations not known  
first floor - two drilling machines  
two milling machines  
two small lathes
3. Management office and finance department
4. Supplies office and office of the Basic Party Organization
5. Main warehouse
- 5a. Open timber yard; fuel store nearby, with 14 days' supplies in reserve
6. Personnel office, porter's lodge, main exit gates
7. Canteen, kitchen, food store. (An unidentified office on the first floor)
8. Warehouse (contents not known)
9. Forge
10. Oxygen cylinder store
11. Fire service garage
12. Galvanizing workshop
- 12a. Warehouse (temporarily empty)
13. Fuel and lubricants depot for motor vehicles
14. Store for non-ferrous metals
15. Slipway for cutters
- 15a. Engine repair workshop
- 16a. Engine overhaul shop, and shop for minor motor vehicle repairs
- 16b. Preparatory shop for iron parts such as ribs and frames.  
Construction of iron cutter hulls.  
Installations: iron cutting machine  
metal sheet cutting machine  
machine for shaping iron parts  
two large machine drills
17. Annex, housing administration department offices

SECRET/CONTROL-U.S.OFFICIALS ONLY

SECRET/CONTROL-U.S.OFFICIALS ONLY

- 4 -

- 18. Battery shop
  - 19. Industrial Guard room
  - 20. Carpenters' shops
    - 20a. Equipment: two rotary saws  
two band saws  
one roughing plane  
two smoothing planes
    - 1st floor: Construction of wooden fittings and interior decorations
  - 21. Mechanical workshops:
    - Equipment: seven medium lathes  
two large lathes  
two milling machines  
two iron shaping machines
  - 22. Ancillary warehouse for iron and non-ferrous materials
- 


50X1-HUM

SECRET/CONTROL-U.S.OFFICIALS ONLY

50X1-HUM

SECRET/CONTROL-J.S.OFFICIALS ONLY

- 52 -



SECRET/CONTROL-J.S.OFFICIALS ONLY